

Summary of the Champlain Towers South NCST Investigation Progress

NCST Advisory Committee Meeting

September 9, 2025

Judith Mitrani-Reiser
Lead Investigator

Glenn R. Bell
Associate Lead Investigator

1

Investigation Overview

2

Timeline of Site/Building
History and Collapse

3

Failure Initiation and
Progression Updates

4

Investigation Schedule

5

Next Steps and Conclusion

1

Investigation Overview



Source: NIST

NIST Engineering Laboratory (EL)

Structures Group (MSSD)

Infrastructure Materials Group (MSSD)

Earthquake Engineering Group (MSSD)

Community Resilience Group (MSSD)

Intelligent Systems & Fire Research Divisions

EL's Disaster Impact Reduction Office

EL's Data, Security, Technology Group

EL's Applied Economics Office

MSSD = Materials and Structural Systems Division

NIST

Physical Measurement Laboratory

Materials Measurement Laboratory

Public Affairs Office

Office of Chief Counsel

Program Coordination Office

Management and Organization Office

Acquisition & Agreements Mgmt. Office

ITL's Statistical Engineering Division

ITL = Information Technology Laboratory

**Collaborate
Coordinate
Cooperate**

Federal

Federal Emergency Mgmt. Agency

U.S. Army Corps of Engineers

U.S. Geological Survey

National Science Foundation

Federal Bureau of Investigation

Department of Defense

NOAA's National Weather Service

Bureau of Reclamation

NOAA = National Oceanic and Atmospheric Administration

Local and State

Miami-Dade County Mayor's Office,
Fire, Police, and Building Departments

Town of Surfside

City of Miami Beach

Florida Division of Emergency Mgmt.

Florida DOT and State Attorney's Office


Virginia Beach Fire Department

USAR Task Forces

DOT = Department of Transportation

USAR= Urban Search & Rescue


- Launch NCST Investigation
- Establish Team
- Secure Funds
- Secure Local Workspace



- Custody of Building Evidence
- Collect Subsurface Evidence
- Conduct Non-Destructive Testing
- Secure Local Workspace




- Complete Wave Propagation Tests
- Collect and Review Records
- Conduct Phase I Interviews
- Initiate Collapse Modeling



- Search for Video Footage
- Measure Physical Evidence
- Develop Prelim Code Check Analysis
- Initiate Corrosion Study






- Launch Invasive Testing
- Launch Structural Testing
- Update Collapse Modeling
- Develop Soil-Structure Interaction 3D Model



- Update Collapse Timeline
- Enhance & Analyze Videos
- Conduct Accelerated Corrosion Testing
- Conduct Mechanical Testing of Materials



- Conduct Phase II Interviews
- Complete Column Tests
- Complete Mechanical Tests of Concrete Cores and Reinforcing Steel Bars
- Evaluate Recovered Hard Drives

■
■
■

YR 1

Jun-Dec
2021

Jan-Jun
2022

YR 2

Jul-Dec
2022

Jan-Jun
2023

YR 3

Jul-Dec
2023

Jan-Jun
2024

YR 4

Jul-Dec
2024

Jan-Jun
2025



- Launch Subsurface Materials Tests
- Complete Testing of Full-Scale Building Replicas
- Update Collapse Timeline
- Assess Failure Scenarios

■
■

- Launch NCST Investigation
- Establish Team
- Secure Funds
- Secure Local Workspace

- Complete Wave Propagation Tests
- Collect and Review Records
- Conduct Phase I Interviews
- Initiate Collapse Modeling

- Launch Invasive Testing
- Launch Structural Testing
- Update Collapse Modeling
- Develop Soil-Structure Interaction 3D Model

- Conduct Phase II Interviews
- Complete Column Tests
- Complete Mechanical Tests of Concrete Cores and Reinforcing Steel Bars
- Evaluate Recovered Hard Drives

YR 1

Jun-Dec
2021Jan-Jun
2022

YR 2

Jul-Dec
2022Jan-Jun
2023

YR 3

Jul-Dec
2023Jan-Jun
2024

YR 4

Jul-Dec
2024Jan-Jun
2025

- Custody of Building Evidence
- Collect Subsurface Evidence
- Conduct Non-Destructive Testing
- Secure Local Workspace

- Search for Video Footage
- Measure Physical Evidence
- Develop Prelim Code Check Analysis
- Initiate Corrosion Study

- Update Collapse Timeline
- Enhance & Analyze Videos
- Conduct Accelerated Corrosion Testing
- Conduct Mechanical Testing of Materials

- Launch Subsurface Materials Tests
- Complete Testing of Full-Scale Building Replicas
- Update Collapse Timeline
- Assess Failure Scenarios

- Launch NCST Investigation

- Establish Team

- Secure Funding

- Secure Local

Update on NIST's NCST Investigation

Partial Collapse of Champlain Towers South in Surfside, Florida

June 2025




JUDITH MITRANI-REISER
Lead Investigator | CTS Collapse
NCST




GLENN BELL
Co-Lead Investigator | CTS Collapse
NCST

CTS Expenditures by Fiscal Year (FY)



- Technical work concludes this calendar year, and is focused on closing out assessments of failure scenarios
- A new contract was awarded to Fed Writers in Dec 2024, and modified in Aug 2025, to support CTS NCSTAR report
- New contracts planned to support NCST outside members and dissemination of findings

Design
Code Enforcement
Construction
Special Inspection
Records Retention Policies
Maintenance
Joint Ownership Properties



Recertification for Occupancy

Structural Health Monitoring

Non-Destructive Evaluation of Foundations

Evacuation

Emergency Response

Design

Code
Enforcement

Construction

Special
Inspection

Records
Retention
Policies

Maintenance


Joint Ownership
Properties



Interviews and Focus Groups



Organizational Outreach



Standards Committees

Recertification
for Occupancy

Structural
Health
Monitoring

Non-
Destructive
Evaluation of
Foundations

Evacuation

Emergency
Response

2



Timeline of Site/Building History and Collapse



Source: NIST

IMPORTANT: ALL DATA ARE PRELIMINARY

- These presentations describe preliminary data gathered to date as well as preliminary analyses of these data. Data and analyses are subject to change.
- Once all data are finalized and analyzed, they will inform a broader understanding of the likely technical cause or causes of the collapse – and NIST’s findings and recommendations.
- These presentations do not constitute NIST findings or recommendations.
- All survey and interview data collection included a consent process that specifies the allowable uses of data and protections of respondents.
- Copyrighted content (such as photographs) appearing in these presentations is used with permission; reproduction, redistribution or reuse may require copyright holder permission, including for content with anonymous attribution/credit.
- Every reasonable effort has been made to identify copyright holders for content (such as photographs) appearing in these presentations.



Site History

1900-1979

CTS Design & Construction

1979-1981

CTS Building History



1981-2021

Champlain Towers South Collapse

Weeks/Days Prior to Collapse



Hours/Minutes Prior to Collapse

Initiation & Progression







Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records


Source: NIST



PRELIMINARY ANALYSIS RESULTS






Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records



Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST





Site
History

1900-1979

CTS Design &
Construction

1979-1981

CTS Building
History



1981-2021

Champlain Towers South Collapse


Weeks/Days
Prior to Collapse

Hours/Minutes
Prior to Collapse

Initiation &
Progression



Source: NIST




~One month before collapse

Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST



©2021 Used with permission



©2021 Used with permission
Annotations from interview with eyewitness.


Source: NIST



Weeks before collapse

Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST




Source: NIST

(vertical scale exaggerated for clarity)

PRELIMINARY ANALYSIS RESULTS

Source: 2021, CTS Receiver
Annotations by NIST.



©2021 Used with permission

Source: NIST




Weeks before collapse

Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST



©2021 Used with permission
Image captured few years before collapse.



Source: NIST (artist rendering based on eyewitness accounts)

PRELIMINARY ANALYSIS RESULTS


Source: NIST




Hours before collapse

Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST




Source: CTS Receiver (original drawing)
Annotations from interview with eyewitness.



Miami Dade County Open Data Hub 2021 (aerial background)
Annotated by NIST




Source: NIST



~Minutes before *tower* collapse

Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST



©2021 Used with permission N.W. East View 1:21:39.128 AM 6/24/2021

©2021 Used with permission

1:22:17.876 AM

1:21:00 1:21:50 1:22:00 1:22:50 1:23:00 1:23:50
1:21:39 1:22:18



**Beach Access
Walkway camera
activated by motion**

**South Face camera
activated by motion**

PRELIMINARY ANALYSIS RESULTS

Timeline of Site/Building History and Collapse is Informed by Interviews, Audio-Visual Data, and Building Records

Source: NIST



PRELIMINARY ANALYSIS RESULTS

CONTENT WARNING:

The following slides contain images, video footage, and other content that some may find disturbing.

Participants desiring to skip this section, please proceed to Section 4 of the talk or step away from the live presentation for approximately ten minutes.

3

Failure Initiation and Progression Updates



South Face Camera, Night of the Partial Collapse

© 2021, Used with permission

1. Collapse Sequence

- The pool deck collapsed more than four minutes before the general collapse of the tower.
- In the tower collapse, Grid Line 9.1 started to drop a second, or a bit more, before 1:22:17 am.
 - The columns on Grid Line K and/or L dropped first.
 - The initial column failures were low in the building.
- There were severe structural movements in the interior of the tower before the precipitous drop of the tower at Grid Line 9.1.

3. Failure Progression

- The vulnerability of the structure where the pool deck met the tower allowed the collapse of the pool deck to progress into the tower.
- The poor resistance to progressive collapse allowed the collapse to spread through the east wing of the tower.

2. Failure Initiation

- The investigation rigorously examines about two dozen possible initiating events for the failure.

Examples lower likelihood initiating events include:

- Karst formation (sinkholes).
- Pile failure.
- Separation of the Level 1 slab from the south basement wall.


Examples of higher likelihood initiating events include:

- Failure of a typical slab-column connection in the pool deck.
 - Design understrength, deviations in construction from requirements, loads added to the pool deck, and material degradation led to critically low margins of safety at the time of failure.
- Shortening of a lower-level column in the tower.
- Local crushing of a slab-beam-column joint at Level 1 on Grid Line 9.1.
 - Design understrength and construction deviations reduced the strength of the structural elements in these latter two initiating events. We continue to assess the impacts of material degradation.

1. Collapse Sequence

- The pool deck collapsed more than four minutes before the general collapse of the tower.
- In the tower collapse, Grid Line 9.1 started to drop a second, or a bit more, before 1:22:17 am.
 - The columns on Grid Line K and/or L dropped first.
 - The initial column failures were low in the building.
- There were severe structural movements in the interior of the tower before the precipitous drop of the tower at Grid Line 9.1.

Update: Eyewitness accounts and alarm system records indicate the start of the pool deck collapse was likely at least seven minutes before the precipitous drop of the tower



© 2021, Used with permission


Where Did the Failure Initiate?


- Scenario I: In the Pool Deck
- Scenario II: In the Tower




Source: 2021, A. Sarmiento


Scenario I: Failure Initiation in the Pool Deck








Scenario I: Failure Initiation in the Pool Deck


















3 Failure Initiation



PRELIMINARY ANALYSIS RESULTS

2. Failure Initiation

- The investigation rigorously examines about two dozen possible initiating events for the failure.

Examples of lower likelihood initiating events include:

- Karst formation (sinkholes).
- Pile failure.
- Separation of the Level 1 slab from the south basement wall.

Examples of higher likelihood initiating events include:


- Failure of a typical slab-column connection in the pool deck.
 - Design understrength, deviations in construction from requirements, loads added to the pool deck, and material degradation led to critically low margins of safety at the time of failure.
- Shortening of a lower-level column in the tower.
- Local crushing of a slab-beam-column joint at Level 1 on Grid Line 9.1.
 - Design understrength and construction deviations reduced the strength of the structural elements in these latter two initiating events. We continue to assess the impacts of material degradation.

Pool Deck Slab-Column Connections Critically Low Margins of Safety at Time of Failure




Laboratory slab-column connection tests

Source: NIST



Finite element modeling

Source: NIST using ATENA software



Critical Shear Crack Theory

Source: ACI

Design Understrength
(largest, pervasive)

Misplaced Slab Reinforcement
(pervasive)

Heavier, More Extensive Planters
(near north side of pool deck)


Added Fill and Paving
(variable)

Corrosion of Slab Reinforcement
(variable)

- Together, caused the bulk of the critically low margins of safety
- Existed from the time construction was complete – 40 years before the partial collapse


PRELIMINARY ANALYSIS RESULTS

Pool Deck Slab-Column Connections Construction Joints in Slab



Source base drawing: Town of Surfside.
Annotated by NIST.







Computational Simulation and Structural Laboratory Tests



Source: NIST




Source: NIST using
ATENA software



Source: ACI



Collapse Evidence




Source: NIST

Recent work indicates that it is **MORE LIKELY** that the failure started in a pool deck slab-column connection than we considered in June

3 Failure Initiation



Source: NIST



2. Failure Initiation

- The investigation rigorously examines about two dozen possible initiating events for the failure.

Examples of lower likelihood initiating events include:




- Karst formation (sinkholes).
- Pile failure.
- Separation of the Level 1 slab from the south basement wall.

Examples of higher likelihood initiating events include:

- Failure of a typical slab-column connection in the pool deck.
 - Design understrength, deviations in construction from requirements, loads added to the pool deck, and material degradation led to critically low margins of safety at the time of failure.
- Shortening of a lower-level column in the tower.
- Local crushing of a slab-beam-column joint at Level 1 on Grid Line 9.1.
 - Design understrength and construction deviations reduced the strength of the structural elements in these latter two initiating events. We continue to assess the impacts of material degradation.

Tower Basement Columns



Columns I-8, K-8, L-8 and M-8 in yellow
Columns I-9.1, K-9.1, L-9.1 and M-9.1 in red



Reinforcement details shown are representative of details found in some specimens of the physical evidence.



Recent work indicates failure initiation by crushing of deteriorated concrete at the base of a tower column is *less likely* than we considered in June

Material and petrographic analyses show no evidence of deterioration of the concrete at the bases of basement columns that resulted in significant loss of strength of that concrete





Recent work indicates failure initiation caused by a short lap splice in a tower basement column is *less likely* than we considered in June

- Structural laboratory tests of basement column replicas showed that short lap splices diminish the basement columns' strength and deformation capacity somewhat, but, absent other contributing factors, not to a level that would have failed a column under the conditions present at the time of the partial collapse
- Columns with short lap splices failed in a brittle and explosive manner in the laboratory, with immediate loss of column capacity. This failure mode is inconsistent with the scenario that the columns shortened but were able to bear sufficient load to not cause the tower to collapse






Recent work indicates failure initiation by crushing of a first-level slab-beam-column joint on Grid Line 9.1 is *less likely* than we considered in June

- During structural laboratory tests, CTS replicas (with the pool deck slab and Beam A constructed as they were prior to the failure of the pool deck) sustained column axial loads greater than the loads estimated to be present at the time of failure




Tower Basement Columns

Columns I-8, K-8, L-8 and M-8 in yellow
Columns I-9.1, K-9.1, L-9.1 and M-9.1 in red



Recent work indicates it is **LESS LIKELY** that the failure started in a tower basement column than we considered in June





s found in



3. Failure Progression


- The vulnerability of the structure where the pool deck met the tower allowed the collapse of the pool deck to progress into the tower.
- The poor resistance to progressive collapse allowed the collapse to spread through the east wing of the tower.

Updates on the following slides





Source all images: NIST


PRELIMINARY ANALYSIS RESULTS




Source: NIST




Source: 2021, M. Santana. Annotated by NIST.




PRELIMINARY ANALYSIS RESULTS




11 Stack Unit Footage



Upper Story Corridor Footage




South Face Camera 05:59:52.372 PM 6/23/2021




South Face Camera 1:22:17.609 AM 6/24/2021


Collapsing middle part of tower is still connected to the east part at Grid Line M, which has not yet dropped







The middle part of tower has separated from the east part in this frame





The collapse progresses into the east part of tower in this frame



PRELIMINARY ANALYSIS RESULTS



Recent work indicates that it is **MORE LIKELY** that the failure started in the pool deck than the tower



Computer vision techniques allow us to track the progression of the partial collapse through the tower


4

Investigation Schedule




Champlain Towers South Investigation Schedule






5

Next Steps and Conclusion



Source: ACI



Source: ASCE

Bringing Technical Work to a Close

- The investigation has employed a rigorous, systematic approach to analysis of the plausible failure scenarios and causes.
- Using a fully integrated, interdisciplinary team, we are near the end of analysis of failure scenarios and expect to complete the technical work of this analysis by the end of CY 2025.

Preliminary Findings

- **It is *more likely* that the collapse initiated in the pool deck than the tower.**
- At the time of the failure, the pool deck's slab-column connections had critically low margins of safety. The bulk of the critically low margins of safety was caused by design understrength and misplaced slab reinforcement.
- The structure had low resistance to progressive collapse, allowing the collapse of the pool deck to spread into and throughout the middle and east parts of the tower.

Report and Recommendations

- We are engaging with key stakeholder groups and will continue to do so to disseminate preliminary analysis results and to gather information that will inform technical and policy recommendations.
- Report drafting has begun but will accelerate following completion of technical work for possible failure initiating events at the end of CY 2025.
- We will provide a detailed public update on our investigative findings in the spring/early summer 2026 and expect to complete drafts of all reports ready for technical and policy review several months after our public update.

NCST Investigation of the Champlain Towers South Collapse

Investigation Overview & Update



Judith Mitrani-Reiser
Lead Investigator
judith.mitrani-reiser@nist.gov

Glenn R. Bell
Associate Lead Investigator
glenn.bell@nist.gov

NIST's Investigation of the Champlain Towers South Partial Collapse

NIST CTS Information

<https://www.nist.gov/champlain>



Public Meeting Videos

<https://www.nist.gov/disaster-failure-studies/champlain-towers-south-collapse-ncst-investigation/public-meeting-videos>



NIST DFS Portal

<https://www.nist.gov/disaster-failure-studies/data-submission-portal>

