


## Background

Two stand alone systems were installed in Tepoztlan, Morelos in 1990. The first system was designed with 16 modules (16S x 1P) for lighting applications with **Arco Solar M75** modules. The second system has a 1S x 8P configuration for pumping application with **Arco Solar M55** modules. The objective of this analysis is to establish a dependence between degradation effects and climate conditions in the north part of Morelos.



Site of installation	Tepoztlan Morelos, Mex 18° 54' N, 99° 01' W 1706 meters above sea level
Climate condition	Maritime temperate climates, Cwb (Köppen classification)
Manufacturer name:	Arco Solar Inc M55 & M75
Name plate data:	M55 Pmax= 55 W, Isc= 3.35 A, Voc= 21.7 V, Imax= 3.13 A, Vmax= 17.6 V. M75 Pmax= 50 W, Isc= 3.35 A, Voc= 19.8 V, Imax= 3.11 A, Vmax= 17.6 V.
Years exposed in Mexico	25 years

## Test methods

Crystalline silicon modules were removed and taken to our facilities for their characterization. Degradation analysis was carried out by:


- ❖ Visual Inspection
- ❖ Infrared thermography
- ❖ IV curves with outdoor natural sun light

IV curves obtained were normalized following the procedure 1 described in IEC-60891, with the translation parameters  $\alpha$  y  $\beta$ , supplied by the PV modules manufacturer.

## Results

### Visual Inspection:

Various types of defects were detected after a thorough visual inspection of the modules:



Arco Solar M55 module:


- ✓ Dark discoloration at cell center
- ✓ Delamination between Semiconductor /Encapsulant near the busbars and edges.
- ✓ Oxidation in the frame
- ✓ Crack cells



Arco Solar M75 module:


- ✓ Light discoloration at the cell center
- ✓ Soiled near the frame.
- ✓ Crack cells

### Infrared Images:



Thermal non-uniformity was found in both models. Multiple hot spots were detected near the positive junction box in Arco Solar M55 and near the negative junction box in Arco Solar M75.

### Electrical performance:



Test Condition	M55					M75				
	Voc (V)	Isc (A)	Vmp (V)	Imp (A)	Pm (W)	Voc (V)	Isc (A)	Vmp (V)	Imp (A)	Pm (W)
Rated @ STC	21.7	3.35	17.60	3.13	55.00	19.80	3.35	15.9	3.11	50
Measured @ STC *	22.9	2.31	13.19	1.64	21.64	20.64	2.31	11.69	1.86	21.74
Measured vs Rated	-1.2	1.04	4.41	1.49	33.56	-0.84	1.04	4.21	1.25	28.26
Measured vs Rated (%)	-5.53	31.04	25.06	47.60	60.65	-4.24	31.04	26.48	40.19	56.52
Annual degradation Rate (%)	-0.22	1.24	1.00	1.90	2.43	-0.17	1.24	1.06	1.60	2.26

Electrical series resistance is calculated using outdoor IV curve; for M55 model it was obtained a value for  $R_s$  of 5.74  $\Omega$ , and 4.57 for M75 module. Since there was no control module, only the values of  $R_s$  are presented

## Conclusions

- The power degradation rate is approximately 2 % per year for the worst module.
- Power degradation is due Isc drop and series resistance increases.
- Although it can not be obtain  $R_s$  increases rate, it can be suggest the increase due the IV curve shape.
- Severe corrosion was found in all the M55 modules.

## References

- [1] Packard, C. E., Wohlgemuth, J. H., & Kurtz, S. R. (2012). *Development of a visual inspection data collection tool for evaluation of fielded PV module condition* (No. NREL/TP-5200-56154). National Renewable Energy Laboratory (NREL), Golden, CO.
- [2] Jordan, D. C., & Kurtz, S. R. (2013). Photovoltaic degradation rates—an analytical review. *Progress in photovoltaics: Research and Applications*, 21(1), 12-29.
- [3] Sánchez-Friera, P., Piliouline, M., Pelaez, J., Carretero, J., & Sidrach de Cardona, M. (2011). Analysis of degradation mechanisms of crystalline silicon PV modules after 12 years of operation in Southern Europe. *Progress in photovoltaics: Research and Applications*, 19(6), 658-666.
- [4] Chandel, S. S., Naik, M. N., Sharma, V., & Chandel, R. (2015). Degradation analysis of 28 year field exposed mono-c-Si photovoltaic modules of a direct coupled solar water pumping system in western Himalayan region of India. *Renewable Energy*, 78, 193-202.
- [5] Ndiaye, A., Charki, A., Kobi, A., Kébé, C. M., Ndiaye, P. A., & Sambou, V. (2013). Degradations of silicon photovoltaic modules: A literature review. *Solar Energy*, 96, 140-151.

### Acknowledges:

The present work was supported by the Renewable Energy Institute (IER-UNAM), through the funding of the Mexican Center for Innovation in Solar Energy (CeMIE-Sol), with the Strategic Project No P29 and the FORDECYT project No. 190603. The author want to thank Ing. Amílcar Reyes Roldán for his support in electrical characterization.