

Sample Environment update 2022


Sergiy Gladchenko

Low-temperature Goniometer



Sample Thermalization Problems at He3 and Dilution Refrigerators





Goniometer Vacuum Can









Goniometer + Can Low-Temperature Test


He3 Insert cooling down






Rotation

Pulse versus Continuous Rotation




Cryostat Rotation and Shielding







Sample Rotation and Shielding




Piezoelectric Motor Operation at Low Temperatures





Time

Piezoelectric Motor Operation at Ultra-Low Temperatures





Time

Auto-refill of LHe and LN system (prototype)

- LN and LHe transfer controlled by Level Meter monitor Model 1700 (standard equipment for SE Wet Cryostats);
- System of solenoid valves and relays start and stop the transfer of cryogenic liquids into the Cryostat;
- To reduce evaporation of Liquid Helium during and between the transfers modified transfer line has been designed;
- Automatic and semi-automatic regime of transfer will be available.


Modification of Helium Transfer tube







Auto-refill of LHe and LN system (prototype)

- LN and LHe transfer controlled by Level Meter monitor Model 1700 (standard equipment for SE Wet Cryostats);
- System of solenoid valves and relays start and stop the transfer of cryogenic liquids into the Cryostat;
- To reduce evaporation of Liquid Helium during and between the transfers modified transfer line has been designed;
- Automatic and semi-automatic regime of transfer will be available.






Auto-refill of LHe and LN system (prototype)



Problems with 10T Magnet



Questions?