HMM Reference NIST Technical Note 2205: Item 8.3 & 9 No Gutters



Item 8.3 & 9 No Gutters – Roof edge without gutters can leave combustible roof materials exposed.

Note: Selected photographs are included to illustrate each HMM hardening item. Additional vulnerabilities or hardening items may be seen in the photographs, but those are highlighted within their specific HMM item.

_			\downarrow		
1	HMM Reference•NIST Technical Note 2205, No Gutters, Table A, Items 8.3 & 9 (Page 58)Project: HMM HouseSize: AScale: 1:70Sheet: 1/1		Hardening Actions: Remove gutter & add metal sheathing Installation Cautions if fascia does not cover roof sheathing Applicable Conditions: Combustible gutter cover, no gutter cover, and/or exposed sheathing Performance Goals: Prevent ignition from embers and prevent accumulation of embers at sheathing intersection Installation Cautions		
1	Notes		Color Key:	F	ire Hazards 🛕
	 Very expensive so expensive ones ar May require subsu drainage such as I 	e available Irface-surface	Black: Roof tiles	Gray: Metal flashing 1 Light Gray/White: Pipe Mottled: Rubble filter	. Flammable debris can accumulate in rubble filter and ignite close to house if not cleaned