NVLAP ON-SITE ASSESSMENT SUMMARY

Please complete this summary and attach it to the original On-Site Assessment Report.

DO NOT LEAVE THIS SUMMARY WITH THE LABORATORY.

Laboratory Name: IBeta					Lab Code: <u>200749-0</u>
Fields of Accreditation: Voting					
Assessor Name(s): Dan Hoolihan - Lead Assessor, Steve Freeman - Technical Assessor					
Dat	e of Pr	re-assessment Review of Quality Manual:	4 Decen	nber 20	<u>006</u>
Dat	e(s) of	On-Site Assessment: 11-14 December 20	06		
		t contains changes to the laboratory's Scop cations. (Please describe in the On-Site Na			
SUI	MMAR	Y AND RECOMMENDATIONS:			
	The laboratory has no nonconformities and no written response to NVLAP is required.				
\boxtimes	The laboratory has nonconformities in the following area(s). I have notified the laboratory of these nonconformities and the requirement to respond to NVLAP in writing about their resolution.				
	4	Management requirements		5	Technical requirements
	4.12	Organization Management system Document control Review of requests, tenders and contracts Subcontracting of tests and calibrations Purchasing services and supplies Service to the customer Complaints Control of nonconforming testing and/or calibration work Improvement Corrective action Preventive action Control of records Internal audits Management reviews		Anne Anne policy	General Personnel Accommodation and environmental conditions Test and calibration methods and method validation Equipment Measurement traceability Sampling Handling of test and calibration items Assuring the quality of test and calibration results Reporting the results x A. Referencing NVLAP accreditation x B. Implementation of traceability y in accredited laboratories r (Specify)
	Based on my findings regarding nonconformities, staff competence, and laboratory procedures, I recommend that another on-site assessment be performed before this laboratory is granted accreditation.				
Signature of Lead Assessor					Date