State Laboratory Contact Information A-Z

	Alabama	
Mailing Address	Shipping Address	Contact Information
Alabama Department of Agriculture & Industries Weights and Measures Laboratory PO Box 3336 Montgomery, AL 36109- 0336	Alabama Department of Agriculture & Industries Weights and Measures Laboratory 1445 Federal Drive Montgomery, AL 36107-1123	Michael Bridges (334) 240-3729 Deandre White (334) 240-7135 Phone: (334) 240-7133 (Office) Fax: (334) 240-7175

Alaska	
Mailing Address	Contact Information
Alaska Department of Transportation & Public Facilities 12050 Industry Way Bldg "O" Suite 6 Anchorage, AK 99515-3593	Garret Brown Roger Holland Phone: (907) 365-1233
2013 - 2014 OWM Certificate of Measuremo 2015 - 2016 OWM Certificate of Measuremo	•

	Arizona	
Mailing Address	Shipping Address	Contact Information
Arizona Metrology	Arizona Department of Weights	Brian Sellers
Laboratory	and Measures	(602) 771-4938
1688 W. Adams St.	4425 West Olive Avenue, Suite	Eric Gaedert
Phoenix, AZ 85007-	134	(602) 771-4928
2606	Glendale, AZ 85302-3844	
		Fax:
		(623) 463-0440
2014 - 2	015 OWM Certificate of Measurem	ent Traceability PDF

2015 - 2016 OWM Certificate of Measurement Traceability PDF

(2015-01-01 to 2015-12-31)

2015 - 2016 OWM Certificate of Measurement Traceability PDF

(Amended -2016-01-01 to 2016-12-31)

NVLAP Scope of Accreditation

Arkansas		
Mailing Address	Contact Information	
Arkansas Bureau of Standards	Nikhil Soman	
4608 W 61st St	Charles Hawkins	
Little Rock, AR 72209-2408	Jill Franke	
·	Tom Pugh	
	Randy Burns	
	Phone:	
	(501) 570-1159	
	Fax:	
	(501) 562-7605	
2015 OWM Certificate	e of Measurement Traceability PDF	
2016 - 2017 OWM Certifi	cate of Measurement Traceability PDF	

Califor	rnia
Mailing Address	Contact Information
California Dept of Food and Agriculture Division of Measurement Standards 6790 Florin Perkins Rd, #100 Sacramento, CA 95828-1812	Tony Gruneisen (916) 229-4858 Phone: (916) 229-3025 (Office) Fax: (916) 229-3064

2014 - 2015 OWM Certificate of Measurement Traceability PDF
2016 OWM Certificate of Measurement Traceability PDF
NVLAP Scope of Accreditation

	Colorado
Mailing Address	Contact Information
Colorado Dept of Agriculture	Diane Wise
3125 Wyandot St	(303) 867-9236
Denver, CO 80211-3824	Kate Smetana
	(303) 867-9244
	Nicholas Brechun
	(303) 867-9232
	Phone:
	(303) 867-4270 (Lab)
	Fax:
	(303) 477-4248
2014 OWM Certificate	of Measurement Traceability PDF
	cate of Measurement Traceability PDF 1-01 to 2015-12-31)
2015 - 2016 OWM Certific	cate of Measurement Traceability PDF

(Amended - 2016-01-01 to 2016-12-31)

Connecticut		
Mailing Address	Shipping Address	Contact Information
Connecticut Food and Standards	Metrology Lab	Ana Maria Feliciano
Division	9 Windsor Ave.	(860) 246-9620
Dept of Consumer Protection	Windsor, CT 06095-4312	Frank Greene
State Office Bldg, Rm 165		(860) 713-6160
165 Capitol Avenue		
Hartford, CT 06106-1659		Fax:
		(860) 706-1236

2015 OWM Certificate of Measurement Traceability PDF 2016 OWM Certificate of Measurement Traceability PDF

District of Co	lumbia
Mailing Address	Contact Information
District of Columbia	Lab Closed
Weights, Measures, and Markets Branch	See State Director's List
1110 U St S.E.	
Washington, DC 20001	
No Certifica	te

Delaw	vare
Mailing Address	Contact Information
Delaware Department of Agriculture	Lab Closed
Weights and Measures Section	See State Director's List
2320 S. DuPont Hwy	
Dover, DE 19901-5515	
No Certif	ficate

Floa	rida
Mailing Address	Contact Information
Florida Department of Agriculture	Megan Money
Division of Consumer Services	Amy Smith
Bureau of Standards	Michael Kruse
3125 Conner Blvd, Lab 2	Ryan DeSutter
Tallahassee, FL 32399-1650	Phone:
	(850) 921-1580
	Fax:
	(850) 921-1593

2014 - 2015 OWM Certificate of Measurement Traceability PDF
 2016 - 2017 OWM Certificate of Measurement Traceability PDF
 NVLAP Scope of Accreditation

Georgia		
Mailing Address	Shipping Address	Contact Information
Georgia Department of	3150 U.S. Highway 41	Kontz Bennett
Agriculture Metrology	Tifton, GA 31794-8877	Brian Grace
Laboratory		Fanny English
P.O. Box 1507		
Tifton, GA 31793		Phone:
		(229) 386-3601
		Fax:
		(229) 386-3365

2014 OWM Certificate of Measurement Traceability PDF
2015 - 2016 OWM Certificate of Measurement Traceability PDF
(2015-01-01 to 2015-12-31)

2015 - 2016 OWM Certificate of Measurement Traceability PDF (Amended - 2016-01-01 to 2016-12-31)

Hawaii		
Mailing Address	Contact Information	
Hawaii Department of Agriculture	Michael Tang	
Quality Assurance Division		
1851 Auiki St	Phone:	
Honolulu, HI 96819-3100	(808) 832-0682	
	Fax:	
	(808) 832-0683	

2013 - 2014 OWM Certificate of Measurement Traceability PDF 2015 - 2016 OWM Certificate of Measurement Traceability PDF

Idaho		
Mailing Address	Shipping Address	Contact Information
Idaho Department of	2216 Kellogg Lane	Kevin Merritt
Agriculture	Boise, ID 83712-8265	(208) 332-8692
Bureau of Weights and		Cindy Stark
Measures		(208) 332-8672
PO Box 790		Stacie Ybarra
Boise, ID 83701-0790		(208) 332-8691
		Fax:
		(208) 334-2378
2014 - 2015 O	WM Certificate of Measureme	ent Traceability PDF
2016 - 2017 O	WM Certificate of Measureme	ent Traceability PDF

Illinois		
Mailing Address	Shipping Address	Contact Information
Illinois Department of	801 Sangamon Ave East	Mike Rockford
Agriculture	Springfield, IL 62702-9281	(217) 785-8480
Bureau of Weights and		Karl Cunningham
Measures Standards		(217) 785-8530
Laboratory		
P.O. Box 19281		
Springfield, IL 62702-9281		

2013 - 2014 OWM Certificate of Measurement Traceability PDF2015 - 2016 OWM Certificate of Measurement Traceability PDF

Indiana		
Mailing Address	Contact Information	
ndiana State Department of Health	Joshua Reagin	
Veights and Measures Laboratory	(317) 356-7078 x229	
525 N. Shadeland Ave, #D3		
Bldg 30 Entrance 12	Fax:	
ndianapolis, IN 46219-1791	(317) 351-2877	

2015 OWM Certificate of Measurement Traceability PDF (2015-01-01 to 2015-06-30) Suspended Effective: 2015-07-01 2016 OWM Certificate of Measurement Traceability PDF [Conditional - 2016-01-01 to 2016-12-31]

Iowa	
Mailing Address	Contact Information
State of Iowa Metrology Laboratory	Lab Closed See State Director's List

2013 OWM Certificate of Measurement Traceability PDF

Laboratory Closed Effective July 1, 2014
2014 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-12-31) PDF

Kansas		
Mailing Address	Shipping Information	Contact Information
Kansas Metrology	Building 282, Earhart St., Forbes Field	Kevin Uphoff
Laboratory	Topeka, KS 66619-0282	(785) 296-2938
PO Box 19282		Keith Arkenberg
Bldg 282, Forbes	6531 SE Forbes Ave. St B	(785) 296-2937
Field	Topeka, KS 66619-0282	Fax:
Topeka, KS 66619- 0282		(785) 296-8298

2014 OWM Certificate of Measurement Traceability PDF

2015 - 2016 OWM Certificate of Measurement Traceability PDF

(2015-01-01 to 2015-12-31)

2015 - 2016 OWM Certificate of Measurement Traceability PDF

(Amended - 2016-01-01 to 2016-12-31)

Kentucky		
Mailing Address	Contact Information	
Kentucky Regulations and Inspections	Jason Glass	
107 Corporate Dr.	Chester Watson	
Frankfort, KY 40601-8311	Bill Baker	
	Casey Logsdon	
	Phone:	
	(502) 573-0282	
	Fax:	
	(502) 573-0303	
2014 OWM Certificate of Measurement Traceability PDF		
2015 - 2016 OWM Certificate of Measurement Traceability PDF		

Los Angeles County		
Mailing Address	Contact Information	
Los Angeles County Department of Agriculture Weights and Measures Metrology Laboratory 11012 Garfield Avenue South Gate, California 90280-7504	Kai Cheung Chow (562) 622-0418 Lina Ng (562) 622-0419 Fax: (562) 861-0278	
2015 OWM Certificate of Measurement Traceability PDF 2016 OWM Certificate of Measurement Traceability PDF		

Louisiana		
Mailing Address	Shipping Address	Contact Information
Louisiana Department of Agriculture and Forestry	5825 Florida Blvd Baton Rouge, LA 70806-4259	Richert Williams
Weights and Measures Division 5825 Florida Blvd	0 /	Phone: (225) 922-1380 Fax:
Suite 5000 Baton Rouge, LA 70806		(225) 923-4877

2014 - 2015 OWM Certificate of Measurement Traceability PDF 2016 OWM Certificate of Measurement Traceability PDF

Maine		
Mailing Address	Shipping Address	Contact Information
Maine Department of	Metrology Lab	Ronald Dyer
Agriculture	333 Cony Rd.	Bradford Bachelder
Conservation & Forestry Div. QA&R 28 State House Station Augusta, ME 04333-0028	Ag Bldg Augusta, ME 04330-0503	Phone: (207) 287-7587 Fax:
Augusta, IVIE 04353-0026		(207) 287-7161

2015 OWM Certificate of Measurement Traceability PDF 2016 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation

Contact Information Elizabeth Koncki Joseph Eccleston
Joseph Eccleston
· ·
Za ala sita a Tutu a vila a
Zacharias Tripoulas
Phone:
(410) 841-5790
Fax:
(410) 841-2765

Laboratory Suspended Effective July 1, 2014
2014 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-06-30) PDF
2014 OWM Certificate of Measurement Traceability
(2014-07-01 to 2014-12-31) PDF

2016 OWM Certificate of Measurement Traceability PDF

Massachusetts		
Mailing Address	Contact Information	
Commonwealth of Massachusetts Metrology Lab	Raymond Costa	
661 (Rear) Highland Avenue	Phone:	
Needham Heights, MA 02494-2229	(781) 444-0219	
	Fax:	
	(781) 444-0891	
2015 OWM Certificate of Mea	asurement Traceability PDF	

2015 OWM Certificate of Measurement Traceability PDF 2016 - 2017 OWM Certificate of Measurement Traceability PDF

Michigan		
Mailing Address	Contact Information	
Michigan Department of Agriculture	Craig VanBuren	
E.C. Heffron Metrology Laboratory	(517) 655-8202 x314	
940 Venture Lane	Dr. Neil Jones	
Williamston, MI 48895-9028	(517) 655-8202 x327	
	Nicholas Santini	
	(517) 655-8202 x316	
	Ryanne Hartman	
	Scott Ferguson	
	Phone:	
	(517) 655-8202 (Office)	
	Fax:	
	(517) 655-8303	

2014 - 2015 OWM Certificate of Measurement Traceability PDF 2016 - 2017 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation

Minnesota		
Mailing Address	Contact Information	
Minnesota Metrology Laboratory	Erik Alfvin	
Department of Commerce	(651) 539-1569	
Division of Weights & Measures	Pete Whebbe	
14305 Southcross Drive	(651) 539-1564	
W Suite 150	Julie Quinn	
Burnsville, MN 55306-7011	(651) 539-1556	
	Dr. Benjamin Fitzpatrick	
	(651) 539-1560	
	Heidi Jones	
	(651) 539-1565	
	Mark Nicollet	
	(651) 539-1566	
	Phone:	
	(651) 539-1555 (Office)	
	Fax:	
	(952) 539-1553	

2015 OWM Certificate of Measurement Traceability PDF
2016 - 2017 OWM Certificate of Measurement Traceability PDF
NVLAP Scope of Accreditation

Mississippi		
Mailing Address	Shipping Address	Contact Information
Mississippi Department of	1000 ASU Dr.	Mel lasigi
Agriculture & Commerce	Lorman, MS 39096-7500	William Bell
Weights and Measures		
Division		Phone:
1000 ASU Dr.,		(601) 877-3802
P.O. Box 1200		Fax:
Alcorn St, MS 39096		(601) 877-3872

2015 OWM Certificate of Measurement Traceability PDF 2016 -2017 OWM Certificate of Measurement Traceability PDF

Missouri		
Mailing Address	Shipping Address	Contact Information
Missouri Department of	1616 Missouri Blvd	Kevin Hanson
Agriculture	Jefferson City, MO 65109-1732	(573) 751-3440
P.O. Box 630		Thomas Hughes
Jefferson City, MO 65102-		(573) 751-9487
0630		
		Fax:
		(573) 751-0281
2015 OWM Certificate of Measurement Traceability		
(2015-01-01 to 2015-12-31) PDF		

2016 OWM Certificate of Measurement Traceability PDF

Montana		
Mailing Address	Contact Information	
Montana Bureau of Weights and Measures 2801 North Cooke St. Helena, MT 59601	David Fraser Tim Lloyd Carol Larkin	
	Phone: (406) 449-2582 Fax: (406) 443-8163	
2015 OWM Certificate of Measurement Traceability PDF 2016 OWM Certificate of Measurement Traceability PDF		

Nebraska	
Mailing Address	Contact Information
Nebraska Division of Weights and Measures 3721 W. Cuming St. Lincoln, NE 68524	Ken Tichota Phone: (402) 471-4292 (Office) (402) 471-2087 (Lab) Fax: (402) 471-6685
No Certificat	re

Nevada		
Mailing Address	Contact Information	
Nevada Division of Measurement Standards Bureau of Weights and Measures 2150 Frazer Avenue Sparks, NV 89431	Mary Gonzales (775) 353-3794 James Kellames (775) 353-3788	
	<i>Fax:</i> (775) 688-2533	

Laboratory Suspended Effective September 1, 2014

2013 - 2014 OWM Certificate of Measurement Traceability PDF (2013-01-01 to 2014-08-31)

2016 OWM Certificate of Measurement Traceability PDF

TA T	TT	1 •
New	Ham	pshire
1 10 11	1 10111	

110W Hampshire		
Mailing Address	Contact Information	
New Hampshire Metrology Laboratory	Timothy L. Osmer	
P.O. Box 2042	Richard P. Cote	
Concord, NH 03302-2042		
	Phone:	
Physical Location:	(603) 271-3700 (Office)	
Division of Weights & Measures	(603) 271-0894 (Lab)	
25 Capitol Street	Fax:	
Concord, NH 03301	(603) 271-1109	

2014 - 2015 OWM Certificate of Measurement Traceability
(Amended - 2015-01-01 to 2015-12-31)
2016 - 2017 OWM Certificate of Measurement Traceability PDF

2016 - 2017 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation

New Jersey

Nailing Address	Contact Information
tate of New Jersey,	Ray Szpond
epartment of Law and Public Safety,	Michael Cecere
ivision of Consumer Affairs,	Kyle Pierson
ffice of Weights and Measures	
261 Routes 1 & 9 South,	Phone:
venel, NJ 07001-1647	(732) 815-4859
	Fax:
	(732) 382-5298

2015 OWM Certificate of Measurement Traceability PDF 2016 - 2017 OWM Certificate of Measurement Traceability PDF

New Mexico		
Mailing Address	Contact Information	
New Mexico Department of Agriculture	Clay Ivey	
Standards and Consumer Services		
3190 S. Espina	Phone:	
MSC 3170	(575) 646-1616	
P.O. Box 30005	Fax:	
Las Cruces, NM 88003-8005	(575) 646-2361	

2015 OWM Certificate of Measurement Traceability PDF2016 OWM Certificate of Measurement Traceability PDFNVLAP Scope of Accreditation

New York		
Mailing Address	Contact Information	
New York Bureau of Weights and Measures	Mike Sikula	
6 Harriman Campus Rd,	Eric Morabito	
Albany, NY 12206-5409		
	Phone:	
Mailing Address:	(518) 457-3452	
10B Airline Dr.	Fax:	
Albany, NY 12235-1000	(518) 457-2552	

2013 OWM Certificate of Measurement Traceability

[A: 2013-01-01 to 2013-6-30] PDF

2013 OWM Certificate of Measurement Traceability

[B: 2013-08-01 to 2013-12-31] PDF

2014 - 2015 OWM Certificate of Measurement Traceability PDF

[2014-01-01 to 2014-12-31] PDF

2015 OWM Certificate of Measurement Traceability

[2015-01-01 to 2015-06-30] PDF

2015 -2016 OWM Certificate of Measurement Traceability

[Conditional - 2015-07-01 to 2016-06-30] PDF

North Carolina		
Mailing Address	Contact Information	
North Carolina Department of Agriculture	Sharon Woodard	
and Consumer Services	Van Hyder	
Standards Laboratory	Robert Rogers	
4040 District Dr.	Ashley Lessard	
Raleigh, NC 27607-6470	Sherry Teachey	
	April Lee	
	Susan Myrick	
	Sharon Pulley	
	Nicholas Cercone	
	Phone:	
	(919) 733-4411	
	Fax:	
	(919) 733-8804	

2015 OWM Certificate of Measurement Traceability PDF
2016 - 2017 OWM Certificate of Measurement Traceability PDF
NVLAP Scope of Accreditation

North Dakota		
Mailing Address	Shipping Address	Contact Information
North Dakota Public Service	605 E. Boulevard Ave	Lab Closed
Commission	Bismark, ND 58505	See State Director's List
605 E. Boulevard Ave		
Dept. 408		
State Capitol 12th Floor		
Bismark, ND 58505-0480		
	No Certificate	

Ohio	
Mailing Address	Contact Information
Ohio Department of Agriculture	Fran Elson-Houston
8995 E. Main Street	Tom Buck
Bldg 5	Ken Johnson
Reynoldsburg, OH 43068-3398	Joseph Morrison
	Daniel Walker
	Phone:
	(614) 728-6290
	Fax:
	(614) 728-6424

2015 OWM Certificate of Measurement Traceability PDF
2016 - 2017 OWM Certificate of Measurement Traceability PDF
NVLAP Scope of Accreditation

Oklahoma		
Mailing Address	Contact Information	
Oklahoma Department of Agriculture	Richard Gonzales	
Bureau of Standards	Jeremy Nading	
2800 N. Lincoln Blvd	Erin Albers	
Oklahoma City, OK 73105-4207		
	Phone:	
	(405) 522-5459	
	Fax:	
	(405) 522-5457	
2015 OWM Certificate of Mea	surement TraceabilityPDF	
2016 OWM Certificate of Mea	surement Traceability PDF	
NVLAP Scope of A	Accreditation	

Oregon	
Mailing Address	Contact Information
Oregon Department of Agriculture	Aaron Aydelotte
Weights and Measures Program	(503) 986-4669
535 Capitol Street NE	Ray Nekuda
Salem, OR 97301-2532	(503) 986-4672
emote Facility (no mail):	Phone:
151 Hawthorne Ave., NE	(503) 986-4667 (Lab)
Salem, OR 97301	Fax:
	(503) 986-4784

2014 - 2015 OWM Certificate of Measurement Traceability PDF 2016 - 2017 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation

Pennsylvania	
Mailing Address	Contact Information
Pennsylvania Standards Lab 2221 Forster St. Rm. G 44 A Harrisburg, PA 17125	Janice M. Pistor (717) 346-8115 James Gownley (717) 787-4707 Chris Drupp (717) 525-5826 Richard Radel, Jr (717) 525-5830 David Welker (717) 525-5828 Dustin Claycomb (717) 525-5829 Linc Williams (717) 525-7109/ (717) 787-0937 Fax: (717) 705-0882
2015 OWM Certificate of N	Measurement Traceability PDF

2015 OWM Certificate of Measurement Traceability PDF
2016 - 2017 OWM Certificate of Measurement Traceability PDF
NVLAP Scope of Accreditation

Puerto Rico	
Mailing Address	Contact Information
Puerto Rico Department of Consumer Affairs	Abner Rodriguez-Valentin
722 Hoare St.	Phone:
Santurce, PR 00908	(787) 724-5153
	Fax:
	(787) 723-3491
No Certificate	

Rhode Island	
Mailing Address	Contact Information
Rhode Island Department of Labor	Lab Closed
610 Manton Ave	See State Director's List
Providence, RI 02909	Phone:
	(401) 457-1867
	Fax:
	(401) 457-1893
No Certific	ate

S	South Carolina	
Mailing Address	Shipping Address	Contact Information
South Carolina Department of	237 Catawba St.	Robert McGee
Agriculture	Columbia, SC 29201-	Terry Wessinger
PO Box 11280	5250	Tim Jones
Columbia, SC 29211-1280		Ben Sease
		Phone:
		(803) 253-4052
2014 - 2015 OWM Ce	ertificate of Measurement Tra	aceability PDF
2016 - 2017 OWM Ce	ertificate of Measurement Tra	aceability PDF

South Dakota		
Mailing Address	Shipping Address	Contact Information
SD Office of Weights and Measures 118 W. Capitol Pierre, SD 57501-2000	SD Office of Weights and Measures 1500 N. Garfield Ave E. Truck Bypass Pierre, SD 57501	Lori Jacobson Ron Peterson Phone: (605) 773-3170 (Lab) (605) 773-3697 (Office)
		Fax: (605) 355-3001

2015 OWM Certificate of Measurement Traceability PDF2016 OWM Certificate of Measurement Traceability PDF

Tennessee		
Mailing Address	Shipping Address	Contact Information
I Department of	430 Hogan Road	Robert G. Williams
riculture	Jennings Building	(615) 837-5144
lington Agriculture	Nashville, TN 37220-9029	Kenneth R. Wilmoth
nter		(615) 837-5159
). Box 40627		
elrose Station		Fax:
ashville, TN 37204-0627		(615) 837-5015
	finate of Management Trans	

2015 OWM Certificate of Measurement Traceability [Conditional] PDF 2016 OWM Certificate of Measurement Traceability [Conditional] PDF

Texas		
Mailing Address	Shipping Address	Contact Information
TX Department of Agriculture	1258 CR 226	Philip Wright
Metrology Laboratory	Giddings, TX 78942	Shauna Keilberg
P.O. Box 1518		Daniel Gibbons
Giddings, TX 78942		Preston Adachi
		Lisa Corn
		Phone:
		(979) 542-3231
		Fax:
		(979) 542-2961

2013 - 2014 OWM Certificate of Measurement Traceability (2013-01-01 to 2013-04-31) PDF

2013 - 2014 OWM Certificate of Measurement Traceability

(2013-05-01 to 2014-12-31) PDF

2015 - 2016 OWM Certificate of Measurement Traceability PDF

2015 - 2016 OWM Certificate of Measurement Traceability PDF

(Amended - 2016-01-01 to 2016-12-31)

Mailing Address		
Mailing Address	Contact Information	
JSDA/GIPSA	Marcus Harwitz	
Master Scale Depot	Al Rupert	
5800 W. 69th St.		
Chicago, IL 60639	Phone:	
	(708) 458-0655	
	Fax:	
	(708) 458-0749	

Utah		
Mailing Address	Contact Information	
UT Department of Agriculture	Brett Gurney	
Division of Regulatory Services	Bill Rigby	
350 N. Redwood Rd		
Box 146500	Phone:	
alt Lake City, UT 84114-6500	(801) 538-7153	
	Fax:	
	(801) 538-4949	
2014 - 2015 OWM Certificate o	of Measurement Traceability PDF	

2016 - 2017 OWM Certificate of Measurement Traceability PDF

Vermont			
Mailing Address	Shipping Address	Contact Information	
Consumer Protection Section	Vermont Weights and	Marc Paquette	
Vermont Weights and	Measures Lab	(802) 793-6744	
Measures Lab	322 Industrial	Scott Dolan	
322 Industrial Dr.	Berlin, VT 05641-5277		
Berlin, VT 05641-5277		Phone:	
		(802) 828-2426 (Office)	
		Fax:	
		(802) 828-5983	
2015 OWM C	॥ ertificate of Measurement ।	Traceability PDF	

2015 OWM Certificate of Measurement Traceability PDF 2016 - 2017 OWM Certificate of Measurement Traceability PDF

Contact Information Archie Corbitt General Email Lab Closed See State Director's List
General Email Lab Closed
Lab Closed
See State Director's List
See State Director's List
Phone:
(340) 773-2226
Fax:
(340) 778-8250

Virginia			
Mailing Address	Contact Information		
VA Metrology Lab	William Loving		
600 North 5th St	William Scott		
Richmond, VA 23219			
	Phone:		
	(804) 786-0479		
	Fax:		
	(804) 371-0206		
2014 - 2015 OWM Cert	ificate of Measurement Traceability PDF		
2016 - 2017 OWM Certificate of Measurement Traceability PDF			
NVLAP Scope of Accreditation			

Washington		
Mailing Address	Shipping Address	Contact Information
WA State	WA State Department of Agriculture (WSDA)	Dan Wright
Department	Metrology Laboratory	
of Agriculture	2747 29th Ave. SW	Phone:
(WSDA)	Tumwater, WA 98512-6104	(360) 753-5042
Metrology		Fax:
Laboratory		(360) 586-4728
P.O. Box		
42560		
Olympia, WA		
98504-2560		
2014	2015 OWW Cortificate of Measurement Traces	bility [Amazandad] DDF

2014 - 2015 OWM Certificate of Measurement Traceability [Amended] PDF
2016 - 2017 OWM Certificate of Measurement Traceability PDF
NVLAP Scope of Accreditation

West Virginia		
Mailing Address	Contact Information	
WV Department of Labor	Anthony O'Brien	
570 McCorkle Ave	Tory Brewer	
St. Albans, WV 25177-1795		
	Phone:	
	(304) 722-0602	
	Fax:	
	(304) 722-0605	
2015 OWM Certificate of Mea	asurement Traceability [Conditional] PDF	
2016 OWM Certificate of Measurement Traceability [Conditional] PDF		

Wisconsin			
Mailing Address	Shipping Address	Contact Information	
WI Weights and Measures	3601 Galleon Run	Justin Lien	
Laboratory	Madison, WI 53718-6921	(608) 224-4913	
Admin. Add.		Jeff Houser	
2811 Agriculture Dr.		(608) 224-4911	
Madison, WI 53718-6777		Richard McCann	
		(608) 224-4910	
		Paul Masterson	
		(608) 224-4908	

2015 OWM Certificate of Measurement Traceability PDF 2016 - 2017 OWM Certificate of Measurement Traceability PDF

Wyoming		
Mailing Address	Contact Information	
WY Department of Agriculture	Robert Weidler	
6607 Campstool Rd	Todd Stiles	
Cheyenne, WY 82002	Phone:	
	(307) 777-7556	
	Fax:	
	(307) 777-1943	
2014 - 2015 OWM Certificate of Mea	surement Traceability PDF	
2016 - 2017 OWM Certificate of Measurement Traceability PDF		