State Laboratory Contact Information A-Z

Alabama		
Mailing Address	Shipping Address	Contact Information
Alabama Department of Agriculture & Industries Weights and Measures Laboratory PO Box 3336 Montgomery, AL 36109- 0336	Alabama Department of Agriculture & Industries Weights and Measures Laboratory 1445 Federal Drive Montgomery, AL 36107-1123	Michael Bridges (334) 240-3729 <i>Phone:</i> (334) 240-7173 (Office) <i>Fax:</i> (334) 240-7175
2014 OW	M Certificate of Measurement Tra	scophility DDE

2014 OWM Certificate of Measurement Traceability PDF2015 OWM Certificate of Measurement Traceability PDF

Alaska		
Mailing Address	Contact Information	
Alaska Department of Transportation & Public Facilities 12050 Industry Way Bldg "O" Suite 6 Anchorage, AK 99515-3593	Garret Brown Roger Holland Phone: (907) 365-1233	
2013 - 2014 OWM Certificate of Measurement Traceability PDF 2015 - 2016 OWM Certificate of Measurement Traceability PDF		

Arizona		
Mailing Address	Contact Information	
Arizona Department of Weights and Measures	Brian Sellers	
4425 West Olive Avenue, Suite 134	Eric Gaedert	
Glendale, AZ 85302-3844		
	Phone:	
	(602) 771-4938	
	Fax:	
	(623) 463-0440	
2014 - 2015 OWM Certificate of Meason	urement Traceability PDF	
2015 - 2016 OWM Certificate of Measurement Traceability PDF		

NVLAP Scope of Accreditation PDF

Arkansas		
Mailing Address	Contact Information	
arkansas Bureau of Standards	Nikhil Soman	
4608 W 61st St	Charles Hawkins	
ittle Rock, AR 72209-2408	Randy Burns	
	Tom Pugh	
	Dorothy Lawson	
	Jill Franke	
	Phone:	
	(501) 570-1159	
	Fax:	
	(501) 562-7605	
2014 OWM Certificate of M		
2015 OWM Certificate of M	leasurement Traceability PDF	

California		
Contact Information		
Greg Boers		
(916) 229-3022		
Tony Gruneisen		
(916) 229-4858		
Phone:		
(916) 229-3025 (Office)		
Fax:		
(916) 229-3064		

2012 - 2013 OWM Certificate of Measurement Traceability PDF 2014 - 2015 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation PDF

Nailing Address	Contact Information
lorado Dept of Agriculture	Diane Wise
125 Wyandot St	(303) 867-9236
Denver, CO 80211-3824	Kate Smetana
	(303) 867-9244
	Nicholas Brechun
	(303) 867-9232
	Phone:
	(303) 867-4270 (Lab)
	Fax:
	(303) 477-4248

Connecticut		
Mailing Address	Shipping Address	Contact Information
Connecticut Food and	Metrology Lab	Ana Maria Feliciano
Standards Division	9 Windsor Ave.	(860) 246-9620
Dept of Consumer Protection	Windsor, CT 06095-4312	Frank Greene
State Office Bldg, Rm 165		(860) 713-6160
165 Capitol Avenue		
Hartford, CT 06106-1659		Fax:
		(860) 706-1236

2014 OWM Certificate of Measurement Traceability PDF 2015 OWM Certificate of Measurement Traceability PDF

District of Columbia		
Mailing Address	Contact Information	
District of Columbia	Lab Closed	
Weights, Measures, and Markets Branch	See State Director's List	
1110 U St S.E.		
Washington, DC 20001		
No Certificate		

Delaware		
Mailing Address	Contact Information	
Delaware Department of Agriculture	Lab Closed	
Weights and Measures Section	See State Director's List	
2320 S. DuPont Hwy		
Dover, DE 19901-5515		
No Certificate		

Florida	
Mailing Address	Contact Information
Florida Department of Agriculture	Davis Terry
Division of Consumer Services	Megan Faircloth
Bureau of Standards	Amy Smith
3125 Corner Blvd, Lab 2	Michael Kruse
Tallahassee, FL 32399-1650	Phone:
	1.10.1101
	(850) 921-1557
	Fax:
	(850) 921-1580
2042 2042 01404 0 115 114 1	AA

2012 - 2013 OWM Certificate of Measurement Traceability PDF
 2014 - 2015 OWM Certificate of Measurement Traceability PDF
 NVLAP Scope of Accreditation PDF

Georgia		
Mailing Address	Shipping Address	Contact Information
Georgia Department of	3150 U.S. Highway 41	Kontz Bennett
Agriculture Metrology	Tifton, GA 31794-8877	Brian Grace
Laboratory		Fanny English
P.O. Box 1507		
Tifton, GA 31793		Phone:
		(229) 386-3601
		Fax:
		(229) 386-3365

2014 OWM Certificate of Measurement Traceability PDF 2015 - 2016 OWM Certificate of Measurement Traceability PDF

Hawaii		
Mailing Address	Contact Information	
Hawaii Department of Agriculture Quality Assurance Division	Michael Tang	
1851 Auiki St	Phone:	
Honolulu, HI 96819-3100	(808) 832-0682	
	Fax:	
	(808) 832-0683	
2013 - 2014 OWM Certificate of Measurement Traceability PDF		
2015 - 2016 OWM Certificate of Measurement Traceability PDF		

Idaho		
Mailing Address	Shipping Address	Contact Information
Idaho Department of	2216 Kellogg Lane	Kevin Merritt
Agriculture	Boise, ID 83712-8265	(208) 332-8692
Bureau of Weights and		Cindy Stark
Measures		(208) 332-8672
PO Box 790		Stacie Ybarra
Boise, ID 83701-0790		(208) 332-8691
		Fax:
		(208) 334-2378
2012 - 2013 O\	WM Certificate of Measureme	nt Traceability PDF
2014 - 2015 O\	WM Certificate of Measureme	nt Traceability PDF

Illinois		
Mailing Address	Shipping Address	Contact Information
Illinois Department of	801 Sangamon Ave East	Mike Rockford
Agriculture	Springfield, IL 62702-9281	(217) 785-8480
Bureau of Weights and		Karl Cunningham
Measures Standards		(217) 785-8530
Laboratory		Matthew Williams
P.O. Box 19281		(217) 785-8530
Springfield, IL 62702-9281		

2013 - 2014 OWM Certificate of Measurement Traceability PDF 2015 - 2016 OWM Certificate of Measurement Traceability PDF

Indiana		
Mailing Address	Contact Information	
Indiana State Department of Health	Jerry Clingaman	
Weights and Measures Laboratory	(317) 356-7078 x226	
2525 N. Shadeland Ave, #D3	Joshua Reagin	
Bldg 30 Entrance 12	(317) 356-7078 x227	
Indianapolis, IN 46219-1791		
	Fax:	
	(317) 351-2877	
2014 OWM Certificate of M	easurement Traceability PDF	
2015 OWM Certificate of M	2015 OWM Certificate of Measurement Traceability PDF	
NVLAP Scope of Accreditation		

Iowa	
Mailing Address	Contact Information
State of Iowa Metrology Laboratory	Lab Closed See State Director's List

2013 OWM Certificate of Measurement Traceability PDF

Laboratory Closed Effective July 1, 2014
2014 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-12-31) PDF

Kansas		
Mailing Address	Shipping Information	Contact Information
Kansas Metrology Laboratory	Building 282, Earhart St., Forbes Field	Kevin Uphoff (785) 862-2415
PO Box 19282 Bldg 282, Forbes Field Topeka, KS 66619-0282	Topeka, KS 66619-0282 6531 SE Forbes Ave.	Keith Arkenberg (785) 862-2453
Торска, ко 00015 0202	St B Topeka, KS 66619-0282	<i>Fax:</i> (785) 862-2460
2014 OWM Certificate of Measurement Traceability PDF		

Kentucky		
Mailing Address	Contact Information	
Kentucky Regulations and Inspections	Jason Glass	
107 Corporate Dr.	Chester Watson	
Frankfort, KY 40601-8311	Bill Baker	
	Casey Logsdon	
	Phone:	
	(502) 573-0282	
	Fax:	
	(502) 573-0303	
2014 OWM Certificate of Measurement Traceability PDF		
2015 - 2016 OWM Certificate of Measurement Traceability PDF		

Los Angeles County		
Mailing Address	Contact Information	
Los Angeles County Department of Agriculture Weights and Measures Metrology Laboratory 11012 Garfield Avenue South Gate, California 90280-7504	Kai Cheung Chow (562) 622-0418 Lina Ng (562) 622-0419 Fax: (562) 861-0278	
2014 OWM Certificate of Measurement Traceability PDF 2015 OWM Certificate of Measurement Traceability PDF		

Louisiana		
Mailing Address	Shipping Address	Contact Information
Louisiana Department of	5825 Florida Blvd	Richert Williams
Agriculture and Forestry	Baton Rouge, LA 70806-4259	Carl Decker
Weights and Measures		
Division		Phone:
PO Box 3098		(225) 922-1380
Baton Rouge, LA 70821-3098		Fax:
		(225) 923-4877

2012 - 2013 OWM Certificate of Measurement Traceability PDF2014 - 2015 OWM Certificate of Measurement Traceability PDF

Maine		
Mailing Address	Shipping Address	Contact Information
Maine Department of	Metrology Lab	Ronald Dyer
Agriculture	333 Cony Rd.	Bradford Bachelder
Conservation & Forestry	Ag Bldg	
Div. QA&R	Augusta, ME 04330-0503	Phone:
28 State House Station		(207) 287-7587
Augusta, ME 04333-0028		Fax:
//agasta, ME 04333 0020		(207) 287-7161

2014 OWM Certificate of Measurement Traceability

[Conditional – 2014-01-01 to 2014-06-30] PDF

2014 OWM Certificate of Measurement Traceability

[Conditional – 2014-09-08 to 2014-12-31] PDF

2015 OWM Certificate of Measurement Traceability PDF

Maryland		
Mailing Address	Contact Information	
Maryland Department of Agriculture 50 Harry S. Truman Pkwy	Zenon M. Waclawiw	
Annapolis, MD 21401-8960	Phone:	
	(410) 841-5790	
	Fax:	
	(410) 841-2765	

2012 - 2013 OWM Certificate of Measurement Traceability PDF

Laboratory Suspended Effective July 1, 2014
2014 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-06-30) PDF
2014 OWM Certificate of Measurement Traceability
(2014-07-01 to 2014-12-31) PDF

Massachusetts		
Mailing Address	Contact Information	
Commonwealth of Massachusetts Metrology Lab	Raymond Costa	
661 (Rear) Highland Avenue	Phone:	
Needham Heights, MA 02494-2229	(781) 444-0219	
	Fax:	
	(781) 444-0891	
2014 OWM Certificate of Me	asurement Traceability PDF	
2015 OWM Certificate of Measurement Traceability PDF		

Michigan		
Mailing Address	Contact Information	
Michigan Department of Agriculture	Craig VanBuren	
E.C. Heffron Metrology Laboratory	(517) 655-8202 x314	
940 Venture Lane	Dr. Neil Jones	
Williamston, MI 48895-9028	(517) 655-8202 x327	
	Nicholas Santini	
	(517) 655-8202 x316	
	Ryanne Hartman	
	Scott Ferguson	
	Phone:	
	(517) 655-8202 (Office)	
	Fax:	
	(517) 655-8303	

2012 - 2013 OWM Certificate of Measurement Traceability PDF 2014 - 2015 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation PDF

Minnesota		
Mailing Address	Contact Information	
Minnesota Metrology Laboratory	Julie Quinn	
Department of Commerce	(651) 539-1556	
Division of Weights & Measures	Dr. Benjamin Fitzpatrick	
14305 Southcross Drive	(651) 539-1560	
W Suite 150	Heidi Jones	
Burnsville, MN 55306-7011	(651) 539-1565	
	Mark Nicollet	
	(651) 539-1566	
	General Contact	
	Phone:	
	(651) 539-1555 (Office)	
	Fax:	
	(952) 539-1553	

2014 OWM Certificate of Measurement Traceability PDF 2015 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation PDF

Mississippi		
Mailing Address	Shipping Address	Contact Information
Mississippi Department of	1000 ASU Dr.	Mel lasigi
Agriculture & Commerce	Lorman, MS 39096-7500	William Bell
Weights and Measures		
Division		Phone:
1000 ASU Dr.,		(601) 877-3802
P.O. Box 1200		Fax:
Alcorn St, MS 39096		(601) 877-3872
2014 OWM Certificate of Measurement Traceability PDF		
2015 OWM Certificate of Measurement Traceability PDF		

Missouri		
Mailing Address	Shipping Address	Contact Information
Missouri Department of	1616 Missouri Blvd	Kevin Hanson
Agriculture	Jefferson City, MO 65109-1732	(573) 751-3440
P.O. Box 630		Thomas Hughes
Jefferson City, MO 65102-		(573) 751-9487
0630		
		Fax:
		(573) 751-0281

2014 - 2015 OWM Certificate of Measurement Traceability PDF
2015 OWM Certificate of Measurement Traceability
(2015-01-01 to 2015-12-31) PDF

Montana		
lailing Address	Contact Information	
ontana Bureau of Weights and Measures	David Fraser	
01 North Cooke St.	Tim Lloyd	
elena, MT 59601	Carol Larkin	
	Phone:	
	(406) 449-2582	
	Fax:	
	(406) 443-8163	
2011 - 2012 OWM Certificate of Mea	surement Traceability PDF	
2015 OWM Certificate of Measur	ement Traceability PDF	

Nebraska		
Mailing Address	Contact Information	
Nebraska Division of Weights and Measures	Craig Olsen	
3721 W. Cuming St.	Ken Tichota	
Lincoln, NE 68524	Phone: (402) 471-4292 (Office) (402) 471-2087 (Lab) Fax: (402) 471-6685	
No Certificate		

Nevada	
Mailing Address	Contact Information
Nevada Division of Measurement Standards	Bart O'Toole
Bureau of Weights and Measures	
150 Frazer Avenue	Phone:
Sparks, NV 89431	(775) 353-3794
	Fax:
	(775) 688-2533
Nevada Division of Measurement Standards	
Bureau of Weights and Measures	
Satellite Laboratory	
2300 McLeod Street	
as Vegas, NV 89104	

Laboratory Suspended Effective September 1, 2014

2013 - 2014 OWM Certificate of Measurement Traceability (2013-01-01 to 2014-08-31) PDF

New Hampshire		
Mailing Address	Contact Information	
New Hampshire Metrology Laboratory	Timothy L. Osmer	
P.O. Box 2042	Richard P. Cote	
Concord, NH 03302-2042		
	Phone:	

Physical Location: (603) 271-3700 (Office)
Division of Weights & Measures (603) 271-0894 (Lab)

25 Capitol Street Fax:

Concord, NH 03301 (603) 271-1109

2012 - 2013 OWM Certificate of Measurement Traceability PDF 2014 - 2015 OWM Certificate of Measurement Traceability

[Amended] PDF
NVLAP Scope of Accreditation PDF

New Jersey **Mailing Address Contact Information** State of New Jersey, Ray Szpond Department of Law and Public Safety, Craig Gerhartz Division of Consumer Affairs, Michael Cecere Office of Weights and Measures 1261 Routes 1 & 9 South, Phone: Avenel, NJ 07001-1647 (732) 815-4859 Fax: (732) 382-5298 2014 OWM Certificate of Measurement Traceability PDF 2015 OWM Certificate of Measurement Traceability PDF

New Mexico	
Mailing Address	Contact Information
New Mexico Department of Agriculture	Steve Sumner
Standards and Consumer Services	Clay Ivey
3190 S. Espina	
MSC 3170	Phone:
P.O. Box 30005	(575) 646-1616
Las Cruces, NM 88003-8005	Fax:
	(575) 646-2361

2014 OWM Certificate of Measurement Traceability PDF 2015 OWM Certificate of Measurement Traceability PDF NVLAP Scope of Accreditation PDF

New York		
Mailing Address	Contact Information	
New York Bureau of Weights and Measures	Robert Acheson	
6 Harriman Campus Rd,	Mike Sikula	
Albany, NY 12206-5409	Bruce Davidson	
	Stephen Timar	
Mailing Address:	Eric Morabito	
10B Airline Dr.		
Albany, NY 12235-1000	Phone:	
	(518) 457-3452	
	Fax:	
	(518) 457-2552	

2013 OWM Certificate of Measurement Traceability

[A: 2013-01-01 to 2013-6-30] PDF

2013 OWM Certificate of Measurement Traceability

[B: 2013-08-01 to 2013-12-31] PDF

2014 - 2015 OWM Certificate of Measurement Traceability PDF

[2014-01-01 to 2014-12-31] PDF

2015 OWM Certificate of Measurement Traceability PDF

NVLAP Scope of Accreditation PDF

North Carolina **Mailing Address Contact Information** North Carolina Department of Agriculture **Sharon Woodard** and Consumer Services Van Hyder Standards Laboratory **Robert Rogers** 4040 District Dr. **Ashley Lessard** Raleigh, NC 27607-6470 **Sherry Teachey** April Lee Susan Myrick **Sharon Pulley** Phone: (919) 733-4411

2014 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-07-14) PDF
2014 OWM Certificate of Measurement Traceability
(2014-07-15 to 2014-12-31) PDF
015 OWM Certificate of Measurement Traceability PD

Fax:

(919) 733-8804

2015 OWM Certificate of Measurement Traceability PDF

NVLAP Scope of Accreditation PDF

Mailing Address	Shipping Address	Contact Information
North Dakota Public Service	605 E. Boulevard Ave	Lab Closed
Commission	Bismark, ND 58505	See State Director's List
605 E. Boulevard Ave		
Dept. 408		
State Capitol 12th Floor		
Bismark, ND 58505-0480		

Ohio		
Mailing Address	Contact Information	
Ohio Department of Agriculture	Fran Elson-Houston	
8995 E. Main Street	Ken Johnson	
Bldg 5	Joe Morrison	
Reynoldsburg, OH 43068-3398	Daniel Walker	
	Phone:	
	(614) 728-6290	
	Fax:	
	(614) 728-6424	
2014 - 2015 OWM Certificate of	Measurement Traceability	
(2014-01-01 to 201	14-07-01) PDF	
2014 - 2015 OWM Certificate of	Measurement Traceability	
(2014-07-01 to 202	14-12-31) PDF	
2015 OWM Certificate of Measurement Traceability		
(2015-01-01 to 201	15-12-31) PDF	
NVLAP Scope of Acc	reditation PDF	

Oklahoma		
Mailing Address	Contact Information	
Oklahoma Department of Agriculture	Richard Gonzales	
Bureau of Standards	Jeremy Nading	
2800 N. Lincoln Blvd	James Willson	
Oklahoma City, OK 73105-4207	Ken Fraley	
	Phone:	
	(405) 522-5459	
	Fax:	
	(405) 522-5457	

2014 - 2015 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-12-31) PDF
2015 OWM Certificate of Measurement Traceability
(2015-01-01 to 2015-12-31) PDF

NVLAP Scope of Accreditation PDF

Oregon		
Mailing Address	Contact Information	
Oregon Department of Agriculture	Aaron Aydelotte	
Weights and Measures Program	(503) 986-4669	
635 Capitol Street NE	Ray Nekuda	
Salem, OR 97301-2532	(503) 986-4672	
Remote Facility (no mail):	Phone:	
151 Hawthorne Ave., NE	(503) 986-4667 (Lab)	
Salem, OR 97301	Fax:	
	(503) 986-4784	
2012 - 2013 OWM Certificate of N	Neasurement Traceability PDF	
2014 - 2015 OWM Certificate of N	Measurement Traceability PDF	
NVLAP Scope of Ac	creditation PDF	

Pennsylvania	
Mailing Address	Contact Information
Pennsylvania Standards Lab	Janice M. Pistor
2221 Forster St.	(717) 346-8115
Rm. G 44 A	James Gownley
Harrisburg, PA 17125	(717) 787-4707
	Chris Drupp
	(717) 525-5826
	Richard Radel
	(717) 525-5830
	Linc Williams
	(717) 525-7109
	David Welker
	(717) 525-5828
	Dustin Claycomb
	(717) 525-5829
	Fax:
	(717) 705-0882

2014 - 2015 OWM Certificate of Measurement Traceability
(2014-01-01 to 2014-12-31) PDF
2015 OWM Certificate of Measurement Traceability
(2015-01-01 to 2015-12-31) PDF
NVLAP Scope of Accreditation PDF

Puerto Rico		
Mailing Address	Contact Information	
Puerto Rico Department of Consumer Affairs 722 Hoare St.	Julio Troche-Figueroa Abner Rodriguez-Valentin	
Santurce, PR 00908	Phone:	
	(787) 724-5153	
	Fax:	
	(787) 723-3491	
No Certificate	e	

Rhode Island		
Mailing Address	Contact Information	
Rhode Island Department of Labor	Lab Closed	
610 Manton Ave	See State Director's List	
Providence, RI 02909		
	Phone:	
	(401) 457-1867	
	Fax:	
	(401) 457-1893	
No Certifica	ate	

Mailing Address	Shipping Address	Contact Information
South Carolina Department of	237 Catawba St.	Robert McGee
Agriculture	Columbia, SC 29201-	Billy Kennington
PO Box 11280	5250	(part-time)
Columbia, SC 29211-1280		Terry Wessinger
		Tim Jones
		Phone:
		(803) 253-4052
		Fax:
		(803) 253-4052

South Dakota		
Mailing Address	Shipping Address	Contact Information
SD Office of Weights and Measures 118 W. Capitol Pierre, SD 57501-2000	SD Office of Weights and Measures 1500 N. Garfield Ave E. Truck Bypass Pierre, SD 57501	Lori Jacobson Ron Peterson Phone: (605) 773-3697 (Office) (605) 773-3170 (Lab) Fax: (605) 355-3001
	Certificate of Measurement Trace Certificate of Measurement Trace	•

Mailing Address	Shipping Address	Contact Information
TN Department of	440 Hogan Road	Robert G. Williams
Agriculture	Jennings Building	(615) 837-5144
Ellington Agriculture	Nashville, TN 37220-9029	Kenneth R. Wilmoth
Center		(615) 837-5159
P.O. Box 40627		
Melrose Station		Fax:
Nashville, TN 37204-0627		(615) 837-5015

2014 OWM Certificate of Measurement Traceability [Conditional] PDF 2015 OWM Certificate of Measurement Traceability [Conditional] PDF

Texas		
Mailing Address	Shipping Address	Contact Information
TX Department of Agriculture	1258 CR 226	Philip Wright
Metrology Laboratory	Giddings, TX 78942	Harvey Fischer
P.O. Box 1518		Shauna Keilberg
Giddings, TX 78942		Daniel Gibbons
		Preston Adachi
		Lisa Corn
		Kayla Michalee
		Phone:
		(979) 542-3231
		Fax:
		(979) 542-2961

2013 - 2014 OWM Certificate of Measurement Traceability (2013-01-01 to 2013-04-31) PDF

2013 - 2014 OWM Certificate of Measurement Traceability (2013-05-01 to 2014-12-31) PDF

2015 - 2016 OWM Certificate of Measurement Traceability PDF

USDA/GIPSA		
Mailing Address	Contact Information	
USDA/GIPSA	Marcus Harwitz	
Master Scale Depot	Al Rupert	
5800 W. 69th St.		
Chicago, IL 60639	Phone:	
	(708) 458-0655	
	Fax:	
	(708) 458-0749	
2014 OWM Certificat	e of Measurement Traceability PDF	
2015 -2016 OWM Certifi	cate of Measurement Traceability PDF	

Utah		
Mailing Address	Contact Information	
UT Department of Agriculture	Brett Gurney	
Division of Regulatory Services	Bill Rigby	
350 N. Redwood Rd		
Box 146500	Phone:	
Salt Lake City, UT 84114-6500	(801) 538-7153	
	Fax:	
	(801) 538-4949	
2012 - 2013 OWM Certificate o	of Measurement Traceability PDF	
2014 - 2015 OWM Certificate o	of Measurement Traceability PDF	

	Vermont		
Mailing Address	Shipping Address	Contact Information	
Consumer Protection Section	Vermont Weights and	Marc Paquette	
ermont Weights and	Measures Lab	(802) 793-6744	
Measures Lab	322 Industrial	Scott Dolan	
322 Industrial Dr.	Berlin, VT 05641-5277		
Berlin, VT 05641-5277		Phone:	
		(802) 828-2426 (Office)	
		Fax:	
		(802) 828-5983	

Virgin Islands		
Mailing Address	Contact Information	
VI Department of Licensing and Consumer Affairs	Archie Corbitt	
Golden Rock Shopping Center	General Email	
Christiansted, St. Croix, VI		
	Lab Closed	
	See State Director's List	
	Phone:	
	(340) 773-2226	
	Fax:	
	(340) 778-8250	
No Certificate	II	

Virginia		
Mailing Address	Contact Information	
VA Metrology Lab	Dale Saunders	
600 North 5th St	William Loving	
Richmond, VA 23219		
	Phone:	
	(804) 786-0479	
	Fax:	
	(804) 371-7790	
2012 - 2013 OWM Certificate of Measurement Traceability PDF		
2014 - 2015 OWM Certificate of Measurement Traceability PDF		
NVLAP Scope of Accreditation PDF		

Washington			
Mailing Address	Shipping Address	Contact Information	
WA State Department	WA State Department of Agriculture (WSDA) Metrology Laboratory	Dan Wright	
of Agriculture	2747 29th Ave. SW	Phone:	
(WSDA)	Tumwater, WA 98512-6104	(360) 753-5042	
Metrology		Fax:	
Laboratory		(360) 586-4728	
P.O. Box			
42560			
Olympia, WA			
98504-2560			

2012 - 2013 OWM Certificate of Measurement Traceability PDF
2014 - 2015 OWM Certificate of Measurement Traceability [Amended] PDF
NVLAP Scope of Accreditation PDF

West Virginia			
Mailing Address	Contact Information		
WV Department of Labor	Anthony O'Brien		
570 McCorkle Ave	Tory Brewer		
St. Albans, WV 25177-1795			
	Phone:		
	(304) 722-0602		
	Fax:		
	(304) 722-0605		
2014 OWM Certificate of Measurement Traceability [Conditional] PDF			
2015 OWM Certificate of Measurement Traceability [Conditional] PDF			

Wisconsin			
Mailing Address	Shipping Address	Contact Information	
WI Weights and Measures	3601 Galleon Run	Justin Lien	
Laboratory	Madison, WI 53718-6921	(608) 224-4913	
Admin. Add.		Jeff Houser	
2811 Agriculture Dr.		(608) 224-4911	
Madison, WI 53718-6777		Richard McCann	
		(608) 224-4910	
		Kevin Meyer	
		(608) 224-4914	

2014 OWM Certificate of Measurement Traceability PDF2015 OWM Certificate of Measurement Traceability PDF

Wyoming		
Mailing Address	Contact Information	
WY Department of Agriculture	Robert Weidler	
6607 Campstool Rd	Todd Stiles	
Cheyenne, WY 82002	Phone:	
	(307) 777-7556	
	Fax:	
	(307) 777-1943	
2013 OWM Certificate of N	Measurement Traceability PDF	

2014 - 2015 OWM Certificate of Measurement Traceability PDF

Office of Weights and Measures