


Test Model 3



Datum Feature F not referenced - justifies placing MCS at center of large hole on flange